

# Germantown/Mount Airy Properties

## Physical Conditions and Needs Assessment

---



### Premises F

### 36 E. Wister

Philadelphia, PA 19144

Submitted to

### PHDC

1234 Market Street, 16th Floor  
Philadelphia, PA 19107

March 2021



Construction Project Managers



## TABLE OF CONTENTS

1	Executive Summary
1.1	General Description
1.2	General Physical Condition
1.3	Opinions of Probable Costs
2	Purpose and Scope
2.1	Purpose
2.2	Site Visit
2.3	Useful Life Estimate
2.4	Tenant Pre-Survey Questionnaire
3	<b>Property Address - System Description and Observations</b>
3.1	Overall General Description
3.1.1	Apartment Unit Types and Unit Mix
3.1.2	List of Apartment Units Inspected
3.2	Site
3.2.1	Topography
3.2.2	Storm Water Drainage
3.2.3	Access and Egress
3.2.4	Paving, Curbing and Parking
3.2.5	Flatwork
3.2.6	Landscaping and Appurtenances
3.2.7	Recreational Facilities
3.2.8	Utilities
3.2.8.1	Water
3.2.8.2	Electricity
3.2.8.3	Natural Gas
3.2.8.4	Sanitary Sewer
3.2.8.5	Special Utility Systems
3.2.8.5.1	Site Lighting
3.3	Structural Frame and Building Envelope
3.3.1	Foundation
3.3.2	Building Frame
3.3.2.1	Floor Frame System
3.3.2.2	Crawl Spaces and Penetrations
3.3.2.3	Roof Frame
3.3.2.4	Flashing & Moisture Protection
3.3.2.5	Attic Spaces, Draft Stops, Roof Vents & Penetrations
3.3.2.6	Insulation
3.3.2.7	Stairs, Railings & Balconies Including Connection to Structure
3.3.2.8	Exterior Doors and Entry System
3.3.3	Facades or Curtain wall
3.3.3.1	Sidewall System
3.3.3.2	Fenestration (Window) System
3.3.4	Roofing and Roof Drainage
3.4	Mechanical and Electrical System
3.4.1	Plumbing
3.4.1.1	Supply and Waste Piping
3.4.1.2	Domestic Hot Water Production
3.4.1.3	Fixtures

3.4.2	Heating
3.4.2.1	Heat Generating Equipment
3.4.3	Air Conditioning and Ventilation
3.4.3.1	Equipment
3.4.3.1.1	Air Conditioning and Ventilation
3.4.3.1.2	Exhaust Systems
3.4.3.2	Distribution
3.4.3.3	Control Systems
3.4.3.4	Sprinkler and Standpipes
3.4.4	Electrical
3.4.4.1	Service, Metering, Distribution Panels
3.4.4.2	Distribution
3.4.4.3	Distribution - Tenant Apartments
3.4.4.4	Lighting - Building Common Area
3.4.4.5	Lighting - Resident Apartments
3.4.4.6	Lighting - Site
3.4.4.7	Emergency Generator
3.5	Vertical Transportation - Elevators
3.6	Life Safety/Fire Protection
3.6.1	Sprinklers and Standpipes
3.6.2	Alarm Systems
3.6.3	Other Systems
3.6.3.1	Intercom System
3.6.3.2	Apartment Emergency Duress System
3.7	Interior Elements
3.7.1	Common Areas
3.7.2	Tenant Spaces
3.7.2.1	Finishes, Wall, Floors
3.7.2.2	Appliances
3.7.2.3	Bath Fixtures and Specialties
3.7.2.4	Kitchen Fixtures and Specialties
3.7.2.5	Millwork, Casework, Cabinets and Countertops
3.7.2.6	Closet Systems
4	Additional Considerations
4.1	Environmental Hazards
5	Opinions of Probable Costs to Remedy Physical Deficiencies
6	Out of Scope Considerations
6.1	Accessibility for Persons with Disabilities
7	Limiting Conditions
8	Exhibits
8.1	Cost Estimates
8.1.1	20 Year Table of Quantities & Annual Estimated Costs
8.1.2	SF Cost Estimate for Full Renovation
8.1.3	Reserve for Replacement Analysis
8.2	Photographic Documentation
8.2.1	Photos Architectural
8.2.2	Photos MPEFP
8.3	Supporting Documentation
8.3.1	Flood and Zoning Maps
8.3.2	Environmental Reports
8.3.3	Tenant Questionnaires

# 1 EXECUTIVE SUMMARY

## 1.1 General Description

The Philadelphia Housing and Development Corporation (PHDC) commissioned BFW Group to conduct a Physical Conditions and Needs Assessment of an inventory of 25 premises in the Germantown and Mount Airy neighborhoods of Philadelphia.

36 E. Wister St is a single family residence owned by the Philadelphia Housing and Development Corporation (PHDC) and managed by the Philadelphia Housing Authority (PHA).

The site measures approximately eighteen feet wide by one hundred and four feet deep and is on the south end of a 5-building attached construction on E. Wister Street. This unit consists of a single-family residence which is wood framed with a stucco exterior front and side elevation. The building is two and a half (2.5) stories tall and is rectangular in shape.

The premises is currently occupied.

This Physical Conditions and Needs Assessment is intended to document the existing conditions of the building to determine critical repair items, short- and long-term physical needs and cost estimates for the aforementioned needs of the structure to serve as an affordable rental housing building. BFW Group and their consultants were engaged by the property owner, Philadelphia Housing and Development Corporation (PHDC), to review existing physical conditions to identify opportunities for, or impediments to, renovations.

## 1.2 General Physical Condition

Building Type: Rowhouse  
Property Age: ~120 yrs.

System Conditions & Observations Summary	Good	Fair	Poor	Action
<b>Site Improvements</b>				
3.2.1 Topography		√		None
3.2.2 Storm Water Drainage		√		Not Accessible
3.2.3 Access and Egress			√	None
3.2.4 Paving, Curbing and Parking		√		None
3.2.5 Flatwork		√		None
3.2.6 Landscaping and Appurtenances			√	Remove excessive vegetative growth in rear and side yard.
3.2.7 Recreational Facilities				N/A
3.2.8 Utilities		√		None

Structural Frame and Building Envelope		Good	Fair	Poor	Action
3.3.1	Foundation		√		Not Visible
3.3.2	Building Frame		√		None
3.3.3	Facades or Curtain Wall			√	Windows need replacement.
3.3.4	Roofing and Roof Drainage			√	Requires further assessment, replacement required
<b>Mechanical, Plumbing, Fire Protection and Electrical Systems</b>					
3.4.1	Plumbing			√	Several leaks require repair. Fixtures should be replaced.
3.4.2	Heating		√		None
3.4.3	Air Conditioning and Ventilation			√	Bathroom exhaust system needs replacement. There is no air conditioning system in the building.
3.4.4	Electrical			√	GFI outlets required in kitchens and bathrooms
<b>Vertical Transportation</b>					
3.5.	Elevators				N/A
<b>Life Safety/Fire Protection</b>					
3.6.1	Sprinklers and Standpipes				N/A
3.6.2	Alarm Systems			√	None
3.6.3	Other Systems				N/A
<b>Interior Elements</b>					
3.7.1	Common Areas				N/A
3.7.2	Tenant Spaces		√		Repair/replace lighting, repaint, replace bathroom flooring and carpets.

### 1.3 *Opinions of Probable Cost*

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs will probably vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested work, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc.

## 2 PURPOSE & SCOPE

### 2.1 Purpose

---

The purpose of this Physical Conditions and Needs Assessment (PCNA) is to identify the following: 1) Critical Repair Items; 2) Twelve-Month Physical Needs; 3) Long-Term Physical Needs; and 4) Costing. For this PCNA, representative samples of the major independent building components were observed and their physical conditions were evaluated including site and building exteriors and interiors.

The Philadelphia Housing and Development Corporation (PHDC) wants to identify the required cost to achieve the following: 1) upgrade all occupied units to meet the Department of Housing and Urban Development's (HUD) Housing Quality Standards (HQS); 2) Stabilize and seal all vacant units/buildings; and 3) Renovate all buildings to meet standards required for the low income housing tax credit program.

The physical condition of building systems and related components are typically defined as being in one of three conditions: Good, Fair or Poor, or a combination thereof. For the purposes of this report, the following definitions are used:

*Good = Satisfactory as-is. Requires only routine maintenance over the evaluation period. Repair or replacement may be required due to a system's estimated useful life.*

*Fair = Satisfactory as-is. Repair or replacement is required due to current physical condition and/or estimated remaining useful life.*

*Poor = Immediate repair, replacement or significant maintenance is required.*

### 2.2 Site Visit

---

The initial building walkthrough was conducted on August 31, 2020. The entire single family home was inspected (100%) along with common areas, stairwells, corridors and basement.

### 2.3 Useful Life Estimate

---

It is our observation that the 36 E. Wister St constructed circa 1900, has experienced normal wear and tear for its type and age.

### 2.4 Tenant Pre-Survey Questionnaire

---

Tenants were requested to complete a pre-survey questionnaire. These questionnaires are included in Section 8 (Exhibits). Information obtained from the questionnaires has been used in the preparation of this report.

### 3 SYSTEM DESCRIPTIONS & OBSERVATIONS

#### 3.1 OVERALL GENERAL DESCRIPTION

---

##### 3.1.1 Apartment Unit Types and Unit Mix

The subject property is a single family home. The unit has a living, kitchen and dining room located on the first floor with a wood stair at the center up to the second and third floor. The second floor has three (3) bedrooms and a shared bathroom. The third floor has a master bedroom with a bathroom and closet with access directly off the master bedroom.

##### 3.1.2 List of Apartment Units Inspected

100% of units were inspected.

#### 3.2 SITE

---

##### 3.2.1 Topography

The building is located on a city block, entrance is on Wister Street. There is no notable topography.

##### 3.2.2 Storm Water Drainage

Aluminum gutters located on either side of pitched roof, with aluminum downspouts.

##### 3.2.3 Access and Egress

Access to the site is from Wister Street, the building is two steps up onto a wood covered porch.

##### 3.2.4 Paving, Curbing and Parking

The building has no dedicated off-street parking or loading zone.

##### 3.2.5 Flatwork

Curbs and sidewalk in the front of the building appear to be in good condition.

##### 3.2.6 Landscaping and Appurtenances

There is an overgrowth of vegetation in the front and back of the house.

##### 3.2.7 Recreational Facilities

There are no recreational facilities associated with this property.

##### 3.2.8 Utilities

Sanitary Sewer: City of Philadelphia

Storm Stewer: City of Philadelphia

Domestic Water: City of Philadelphia

Electric Service: PECO Energy Company

Natural Gas Service: Philadelphia Gas Works

###### 3.2.8.1 Water

Domestic water and sanitary piping were not able to be assessed.

#### 3.2.8.2 Electricity

This unit has a 60amp 120/240-volt panel powered from PECO meters for lighting and power which are in poor to good condition.

#### 3.2.8.3 Natural Gas

Incoming gas service from PGW is intact and in good condition. There is a gas meter located in a small closet at the entrance which looks to be in good condition as well.

#### 3.2.8.4 Sanitary Sewer

Not visible for inspection.

#### 3.2.8.5 Special Utility Systems

There are no special utility systems in the building.

##### 3.2.8.5.1 Site Lighting

There is no site lighting at this building.

### 3.3 *STRUCTURAL FRAME & BUILDING ENVELOPE*

---

#### 3.3.1 **Foundation**

Likely masonry (not visible for assessment).

#### 3.3.2 **Building Frame**

##### 3.3.2.1 Floor Frame System

The floor framing consists of wood joists spanning left to right.

##### 3.3.2.2 Crawl Spaces and Penetrations

Not visible for assessment.

##### 3.3.2.3 Roof Frame

Roof was not visible for assessment but is likely wood rafter construction. The roof appears to be a 10 or 12 on 12 pitch roof.

##### 3.3.2.4 Flashing & Moisture Protection

Not visible for assessment.

##### 3.3.2.5 Attic Spaces, Draft Stops, Roof Vents & Penetrations

Not visible for assessment.

##### 3.3.2.6 Insulation

Not visible for assessment.



### 3.3.2.7 Stairs, Railings & Balconies

The staircase is of wood construction. Carpeting along the stairs has been removed. The handrail from the second to third floor is missing and requires replacement.

*Observations/Comments:*

*Add a railing along the stairs on all the floors.  
Install carpeting or refinish wood stairs.*

### 3.3.2.8 Exterior Doors and Entry Systems

Exterior doors to the building appear to be wood.

*Observations/Comments:*

*Replacement of doors should be considered for security and energy efficiency.*

## 3.3.3 Facades or Curtain Wall

### 3.3.3.1 Sidewall System

Exterior cladding consists of a stucco like exterior on the front and side facades. Rear façade consists of vinyl siding which is continuous with adjacent properties.

*Observations/Comments:*

*Repair any cracks and/or damage in stucco exterior.*

### 3.3.3.2 Fenestration (Window) Systems

Exterior windows were observed to be vinyl insulated glass pane with applied mullions.

*Observations/Comments:*

*Replacement of windows should be considered for security and energy efficiency.*

## 3.3.4 Roofing and Roof Drainage

Roof appears to be a 3 tab asphalt shingle nearing the end of its useful life.

*Observations/Comments:*

*Replace asphalt shingles in the near future.*

## 3.4 MECHANICAL AND ELECTRICAL SYSTEM

---

### 3.4.1 Plumbing

#### 3.4.1.1 Supply and Waste Piping

Domestic water and sanitary piping were not able to be assessed.

#### 3.4.1.2 Domestic Hot Water Production

Domestic hot water is provided by a gas fired 30- gallon tank type water heater located in the unit. Domestic water heater by Bradford White is in an excellent condition.

### 3.4.1.3 Fixtures

Plumbing fixtures are in adequate condition.

#### *Observations/Comments:*

*Fixtures should be replaced for better performance.*

## 3.4.2 Heating

### 3.4.2.1 Heating Generating Equipment

This house is designed to be heated via gas fired vertical furnace. This is a forced air, heating only unit. Furnace flue is connected adequately. Furnace is in good condition.

## 3.4.3 Air Conditioning and Ventilation

### 3.4.3.1 Equipment

#### 3.4.1.1 Air Conditioning and Ventilation

There are no air conditioning systems in the building.

#### 3.4.1.2 Exhaust Systems

Bathroom exhaust systems appear in poor condition and should be replaced.

#### *Observations/Comments:*

*Flues were adequately connected, and the system was working effectively*

### 3.4.3.2 Distribution

See Section 3.4.3.1 above.

### 3.4.3.3. Control Systems

Thermostat was defaced and should be replaced.

### 3.4.3.4 Sprinkler and Standpipes

There is no sprinkler system in this building.

## 3.4.4 Electrical

### 3.4.4.1 Service, Metering, Distribution Panels

Electricity was on and working in this house. This unit has a 60amp 120/240-volt panel powered from PECO meters for lighting and power which are in poor to good condition.

#### *Observations/Comments:*

*GFI outlets are required in the kitchen and bathrooms.*

#### 3.4.4.2 Distribution

See 3.4.4.1 above

#### 3.4.4.3 Distribution - Tenant Apartments

See 3.4.4.1 above

#### 3.4.4.4 Lighting - Building Common Area

There is emergency lighting in the hallways but not in individual units.

#### 3.4.4.5 Lighting - Resident Apartment

Lighting in the building appears functional and adequate.

#### 3.4.4.6 Lighting - Site

The building has no exterior lighting, beyond the public street lights.

#### 3.4.4.7 Emergency Generator

The building does not have an emergency generator.

### 3.5 *VERTICAL TRANSPORTATION*

---

3.5.1 There are no elevators in this building.

### 3.6 *LIFE SAFETY/FIRE PROTECTION*

---

#### 3.6.1 **Sprinklers and Standpipes**

There is no sprinkler system in this building.

#### 3.6.2 **Alarm Systems**

There is a battery-operated smoke detector and multiple carbon monoxide detectors.

#### 3.6.3 **Other Systems**

##### 3.6.3.1 Intercom System

There is no intercom system in the building.

##### 3.6.3.2 Apartment Emergency Duress System

There is no emergency duress system in the building.

### 3.7 *INTERIOR ELEMENTS*

---

#### 3.7.1 Common Areas

This is a single family home.

## 3.7.2 Tenant Spaces

### 3.7.2.1 Finishes, Wall, Floors

The living room floors consisted of what appear to be vinyl flooring with a wooden base. The flooring on the second floor hallway has been replaced with a vinyl plank. The flooring on the third floor appears to be a vinyl tile in fair condition. Typical finishes throughout the dwelling consisted of gypsum board walls and ceilings. Finishes were generally in good condition.

#### *Observations/Comments:*

*Replacement of the bathroom flooring is recommended.*

*Existing carpets should be removed and replaced.*

*All walls should be repainted.*

*In all cases floor joists were not accessible for visual inspection.*

### 3.7.2.2 Appliances

Good to fair condition.

### 3.7.2.3 Bath Fixtures and Specialties

The second floor bathroom appears to have an upgraded vanity. The original tub and fiberglass surround were still in place. The surround and tub will likely need to be replaced in due course.

#### *Observations/Comments:*

*There was some evidence of water infiltration around the surround in the second floor bathroom.*

*Wall patch at the back of the bathtub along the hallway is of poor workmanship.*

*Recalking of bath tub surrounds is required.*

### 3.7.2.4 Kitchen Fixtures and Specialties

The kitchen countertop has been replaced with granite which is in good condition. The double bowl stainless sink has also been replaced along with the kitchen faucet. The kitchen backsplash appears to be of vinyl plank type material.

### 3.7.2.5 Millwork, Casework, Cabinets and Countertops

The upper cabinets have been removed. Lower cabinets were covered with a material and were not visible for inspection.

### 3.7.2.6 Closet Systems

The washer/dryer closet had the doors removed. A curtain was installed in place of the doors.

## 4 ADDITIONAL CONSIDERATIONS

### 4.1 ENVIRONMENTAL HAZARDS

---

Lead-based paint, lead-based water, and asbestos testing were completed for this premises.

No lead-based paint or lead-based water was detected in any of the materials sampled.

A radon sample produced a level of 5.8 picocuries per liter (pCi/L) which is above the United States Environmental Protection Agency's (US EPA) recommended indoor residential level of 4 pCi/L.

*Observations/Comments:*

*As of the date of this report work is planned to address radon levels in the premises. The environmental firm engaged to complete work has noted that mitigation measures planned do not guarantee that levels will decrease to below actionable levels.*

## 5 OPINIONS OF PROBABLE COSTS TO REMEDY PHYSICAL DEFICIENCIES

The 20-year table of quantities and annual costs are included in Exhibit 8.1.1, 8.1.2 and 8.1.3. These cover general repairs that apply to the building components site wide and repairs that apply to specific components on site. Based upon site observations and information received from our interviews, the estimated costs are opinions of probable expenditures based upon readily observable conditions and experience with past costs for similar properties. The costs are net of construction management fees and design fees. Actual costs may vary depending on such matters as design, materials, equipment or systems selected, field conditions, phasing of work, management, and unknown factors.

## 6 OUT OF SCOPE CONSIDERATIONS

### 6.1 *Accessibility for Persons with Disabilities*

---

This building does not meet requirements for ADA accessibility.

## 7 LIMITING CONDITIONS

BFW has no control over the cost of labor, materials, equipment, or services furnished by others. It is anticipated that the annual escalation in construction costs increase would be two and a half percent (2.5%) per year.





8.1.1 20 Year Table of Quantities & Annual Estimated Costs

---

**Vacant Units/Buildings** - Estimates provided are for stabilization of unit with renovation to HQS standards in year 5.

**Occupied Units** - Estimates provided to bring units up to HQS standards.

DIVISION	CAPITAL EXPENSE CATEGORY	DESCRIPTION / COMMENTS	CONDITION	Action	EUL (yr)	EFFECTIVE AGE (yr)	RUL (yr)	QUANTITY	UNIT OF MEASURE	UNIT COST	TOTAL COST	CRITICAL REPAIRS
General Requirement	Permitting	2% of the total cost of each respective project									\$697	\$520
	Contingency	10% of the total cost of each respective project									\$3,486	\$2,600
	Overhead and Profit	2.5% of the total cost of each respective project									\$871	\$650
	SubTotal										\$5,054	\$3,770
Site Construction/Existing Conditions	Radon Remediation	High Radon levels detected in first floor sample	Poor	Criterion Lab recommends installing a vent system in the basement to reduce radon levels	N/A	N/A	N/A	N/A	N/A	\$2,595.00	\$2,595	\$2,595
	SubTotal										\$2,595	\$2,595
Woods, Plastics and Composites	Bathrooms	2nd Fl Bathroom vanity	Good	Replace at EUL	25	20	5	1	EA	\$400.00	\$400	\$400
	Stairs	Wood Stairs	Poor	Repair	50	20	30	40	LF	\$100.00	\$4,000	\$4,000
		Interior Railings	Poor	Install	20	20	0	40	LF	\$40.00	\$1,600	\$1,600
	SubTotal										\$6,000	\$5,600
Openings	Windows	Exterior Windows vinyl insulated glass pane with applied mullions	Fair	Replace damaged window	30	20	10	1	EA	\$800.00	\$800	\$800
	Doors	Washer/Closet Dryer Doors were removed	N/A	Replace washer/dryer doors	20	20	0	1	EA	\$900.00	\$900	\$900
	SubTotal										\$1,700	\$800
Finishes	Finishes	Gypsum wallboard and ceiling (throughout)	Good	Repair/paint and replace damage drywall	35	20	15	200	SF	\$8.00	\$1,600	\$1,600
	Flooring	Carpet on stairs removed	N/A	Replace carpet on stairs	6	20	0	400	SF	\$6.00	\$2,400	\$2,400
		3rd floor Master Bedroom vinyl tile floor	Fair	Demo and replace	15	20	0	200	SF	\$10.00	\$2,000	\$2,000
	Bedroom	Wall patched at back of the bathtub	Poor	Repair and repaint	35	20	15	20	SF	\$8.00	\$160	\$160
SubTotal										\$6,160	\$4,400	
Specialties	Bathrooms	2nd floor Bathtub & fiberglass surround; evidence of water infiltration around surround	Poor	Investigate water infiltration and caulk	40	20	20	1	EA	\$300.00	\$300	\$300
	SubTotal										\$300	\$300
Furnishings	Kitchen	Kitchen Upper Cabinets	Poor	Replace upper cabinets	20	20	0	15	LF	\$150.00	\$2,250	\$2,250
		Kitchen Lower Cabinets were covered	N/A	Investigate condition of lower cabinets	20	20	0	15	LF	\$150.00	\$2,250	\$2,250
	SubTotal										\$4,500	\$0
Mechanical, Electrical, Plumbing and Fire Alarm/Suppression	HVAC	Supply and return grilles	Poor	Replace	20	20	0	20	EA	\$50.00	\$1,000	\$1,000
		Thermostat	Poor	Replace thermostat	15	20	0	16	EA	\$300.00	\$300	\$300
		Bathroom exhaust fan	Poor	Replace exhaust fan	15	20	0	16	EA	\$500.00	\$1,000	\$1,000
	Kitchen	Kitchen double bowl stainless sink	Good	Replace at EUL	50	20	30	1	EA	\$800.00	\$800	\$800
		Kitchen Faucet	Good	Replace at EUL	15	20	0	1	EA	\$500.00	\$500	\$500
	SubTotal										\$3,600	\$2,300
Electrical	Electrical Service	60-amp service, panels and wiring (including outlets switches and other power controls)	Poor	Upgrade to 200-amp service, replace all panels and rewire throughout	50	20	30	N/A	N/A	\$10,000.00	\$10,000	\$10,000
	SubTotal										\$10,000	\$10,000
	<b>Total</b>										\$39,909	\$29,765



## 8.1.2 SF Cost Estimate for Full Renovation

---

### **Basis of estimate**

This estimate's purpose is to provide a conceptual cost basis for the renovation or replacement of a particular building or property. The estimate will include construction costs only. The costs are based on the average per square foot construction costs in the greater Philadelphia area for low income housing. Per square foot costs will differ depending on the type and function of the property, scope of work and current condition of the property.

<b>975 SF Renovation - Premises F 36 E Wister St</b>		
<b>ITEM</b>	<b>Total</b>	<b>\$/SF</b>
DEMOLITION	\$ 17,550.00	\$ 18.00
SITework	\$ 2,925.00	\$ 3.00
LANDSCAPE & IRRIGATION	\$ 2,925.00	\$ 3.00
CONCRETE	\$ 3,900.00	\$ 4.00
MASONRY	\$ 4,875.00	\$ 5.00
STRUCTURAL STEEL	\$ -	\$ -
METAL FABRICATIONS	\$ -	\$ -
ROUGH CARPENTRY	\$ 9,750.00	\$ 10.00
ARCHITECTURAL WOODWORK	\$ -	\$ -
THERMAL & MOISTURE PROTECTION	\$ 2,925.00	\$ 3.00
FIREPROOFING	\$ 975.00	\$ 1.00
SEALANTS	\$ 1,950.00	\$ 2.00
WINDOWS	\$ 11,700.00	\$ 12.00
DOORS / FRAMES / HARDWARE	\$ 7,800.00	\$ 8.00
STOREFRONT / GLAZING	\$ -	\$ -
INTERIOR GLASS	\$ -	\$ -
DRYWALL	\$ 4,875.00	\$ 5.00
TILE	\$ 3,900.00	\$ 4.00
ACOUSTIC CEILINGS	\$ -	\$ -
CARPET	\$ 7,800.00	\$ 8.00
PAINTING	\$ 4,875.00	\$ 5.00
WALL COVERINGS	\$ -	\$ -
SPECIALTIES	\$ 3,900.00	\$ 4.00
EQUIPMENT	\$ 3,900.00	\$ 4.00
FURNISHINGS	\$ 1,950.00	\$ 2.00
CONVEYING	\$ -	\$ -
FIRE PROTECTION	\$ 1,950.00	\$ 2.00
PLUMBING	\$ 7,800.00	\$ 8.00
HVAC	\$ 11,700.00	\$ 12.00
ELECTRICAL	\$ 4,875.00	\$ 5.00
COMMUNICATIONS	\$ 975.00	\$ 1.00
ELECTRONIC SAFETY & SECURITY	\$ 975.00	\$ 1.00
GENERAL REQUIREMENTS	\$ 3,900.00	\$ 4.00
<b>Subtotal</b>	<b>\$ 130,650.00</b>	<b>134</b>
Construction Contingency - 10%	\$ 13,065.00	\$ 13.40
Subcontractor Insurance - 2%	\$ 2,613.00	\$ 2.68
Design Contingency - 2%	\$ 2,613.00	\$ 6.70
Overhead & Profit - 2.5%	\$ 3,266.25	\$ 3.35
Permits - 1.5%	\$ 1,959.75	\$ 2.68
Performance & Payment Bonds - 2%	\$ 2,613.00	\$ 2.68
<b>Grand Total</b>	<b>\$ 156,780.00</b>	<b>165</b>











Photos by: VP on 8/31/20


**Photo No. 1**

Depicts entry door.



**Photo No. 2**

View of living room.



**Photo No. 3**

Panning 180 degrees from previous photo. Additional view of living room area.



Photos by: VP on 8/31/20

**Photo No. 4**

View of kitchen.



**Photo No. 5**

Panning left from previous photo. Additional view of kitchen.



**Photo No. 6**


Panning left from previous photo. View of dining area and washer/dryer closet on left.



Photos by: VP on 8/31/20


**Photo No. 7**

View of stairs leading to second and third floors.



**Photo No. 8**

Depicts view of bathtub and shower surround at second floor bathroom.





Photos by: VP on 8/31/20

**Photo No. 9**

Depicts view of second floor bathroom.



**Photo No. 10**

Depicts view of bedroom at second floor.



**Photo No. 11**

Depicts view of bedroom closets.



Photos by: VP on 8/31/20


**Photo No. 12**

Depicts hallway at second floor landing.



**Photo No. 13**

Depicts view of second bedroom at second floor.



Photos by: VP on 8/31/20

**Photo No. 14**

Depicts stairs leading to third floor. Note railing at stair has been removed.



**Photo No. 15**

Depicts view of third floor bathroom.





Photos by: VP on 8/31/20


**Photo No. 16**

Panning down from previous photo. Closer view of water closet.




**Photo No. 17**

View of master bedroom located at third floor.



**Photo No. 18**

View of master bedroom closets and entrance to master bathroom.



CC:

8.2.2 Photos MPEFP

---

MEP



Hot water heater fairley



Supply grill



Thermostat with exposed wire




Side of furnace



Light switch in good shape




### FEMA Flood Zone Map



### FEMA Flood Zone Information


36 E. Wister Street is located in Flood Zone X which represents areas determined to be outside the 0.2% annual chance floodplain as identified by Floor Insurance Rate (FIRM) map number 4207570095G issued by the National Flood Insurance Program (NFIP). 36 E. Wister Street is located in EPA Radon Zone 3, indicating a low potential for the presence of Radon and a predicted average indoor radon screening level of less than 2 pCi/L.

### Aerial





City of Philadelphia Zoning Map



Zoned RSA - 5 - Residential Single Family Attached-5

Allows for detached or semi-detached single family dwellings, duplexes and places of worship.

### 8.3.2 *Environmental Reports*

---



October 9, 2020

**Attention:** PHDC Germantown CNA

**Reference:** Water Sampling for Lead  
36 E. Wister Street, Philadelphia, PA  
Criterion's Project Number: **201379**

On August 31, Criterion Laboratories, Inc. (Criterion) collected a water sample 36 E. Wister Street, Philadelphia, PA to be analyzed for lead.

A 250 milliliter (ml), first draw and a Flush sample was collected from two locations at the address. These samples were analyzed at Criterion in Bensalem, PA using the Graphite Furnace Atomic Absorption Method (EPA Method 200.9).

The Environmental Protection Agency (EPA) has established a current Action Level for lead in public drinking water of 0.015 milligrams per liter (mg/L) or 15 parts per billion (ppb).

The water samples collected from the kitchen and bathroom at 36 E. Wister Street indicated a lead concentration of <2.5 ppb, which is below the EPA Action Level.

Sincerely,

A handwritten signature in black ink, appearing to read 'Melissa Billingsley', is written over a light gray circular stamp.

Melissa Billingsley  
Project Manager

Attachment



## Results of Lead in Drinking Water

Client	<u>BFW Group, LLC</u>	Site Address	<u>Germantown Properties Philadelphia, PA</u>	Sample Date	<u>8/31/2020</u>
Project #	<u>201379</u>			Sample Received Date	<u>8/31/2020</u>
Collected By	<u>Criterion Laboratories, Inc.</u>	Analyzed By	<u>Marrs, Collin</u>	Sample Analysis Date(s)	<u>9/2/2020</u>

Sample Number	Location / Description	Lead (ppb)	Reporting Limit (ppb)
201379-07-023-01-01	Kitchen 1st Draw - 250 ml 40 E. Wister Street	< 2.5	2.5
201379-07-023-01-02	Kitchen Flush Draw - 250 ml 40 E. Wister Street	< 2.5	2.5
201379-07-023-01-03	Bathroom 1st Draw - 250 ml 40 E. Wister Street	< 2.5	2.5
201379-07-023-01-04	Bathroom Flush Draw - 250 ml 40 E. Wister Street	< 2.5	2.5
201379-07-023-01-05	Kitchen 1st Draw - 250 ml 63 E Wister 1st Floor Unit Kitchen	< 2.5	2.5
201379-07-023-01-06	Kitchen Flush Draw - 250 ml 63 E Wister 1st Floor Unit Kitchen	< 2.5	2.5
201379-07-023-01-07	Kitchen 1st Draw - 250 ml 63 E Wister 2nd Floor Unit Kitchen	< 2.5	2.5
201379-07-023-01-08	Kitchen Flush Draw - 250 ml 63 E Wister 2nd Floor Unit Kitchen	< 2.5	2.5
201379-07-023-01-09	Kitchen 1st Draw - 250 ml 36 E Wister Street	< 2.5	2.5
201379-07-023-01-10	Kitchen Flush Draw - 250 ml 36 E Wister Street	< 2.5	2.5
201379-07-023-01-11	Bathroom 1st Draw - 250 ml 36 E Wister Street	< 2.5	2.5
201379-07-023-01-12	Bathroom Flush Draw - 250 ml 36 E Wister Street	< 2.5	2.5
201379-07-023-01-13	Kitchen 1st Draw - 250 ml 4949 Germantown Avenue Unit C	< 2.5	2.5
201379-07-023-01-14	Kitchen Flush Draw - 250 ml 4949 Germantown Avenue Unit C	< 2.5	2.5
201379-07-023-01-15	Bathroom Flush Draw - 250 ml 4949 Germantown Avenue Unit C	< 2.5	2.5
201379-07-023-01-16	Bathroom 1st Draw - 250 ml 4949 Germantown Avenue Unit C	< 2.5	2.5

Sample Count 16

James A. Weltz, CIH, Technical Director

EPA Action Limit is 15.0 ppb (parts per billion). Criterion Laboratories, Inc. bears no responsibility for sample collection activities of non-Criterion personnel. Results apply to sample(s) as received. This report relates only to the samples reported above, and when reproduced, must be in its entirety. QC data associated with this sample set is within acceptable limits. Samples were received in good condition, unless otherwise noted.

Note: If your project number ends with an "R", it is a revised report and replaces the original document in full. Samples are analyzed by Criterion Laboratories, Inc. using EPA Method 200.9: Lead by Graphite Furnace Atomic Absorption (GFAA) and CLI Method 417.

Criterion Laboratories, Inc. (ID 100424) is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the IHLAP; EMLAP and ELLAP accreditation programs for Polarized Light Microscopy (PLM), Phase Contrast Microscopy (PCM); Air-Direct Examination; and Airborne Dust, Paint, Settled Dust by Wipe and Soil for Fields of Testing as documented by the Scope of Accreditation Certificate and associated Scope. Additionally, Criterion Laboratories, Inc. is certified by the Center for Disease Control (CDC) Environmental Legionella Isolation Techniques Evaluation (ELITE) Program for the determination of Legionella in water by culture and holds accreditation from the National Voluntary Laboratory Accreditation Program (NVLAP ID 102046-0) for the determination of asbestos in bulk samples by Polarized Light Microscopy (PLM). This test report must not be used to claim product endorsement by NVLAP, NIST, AIHA or any agency of the US Government. Unless specifically listed as above, these test results are not covered under AIHA-LAP, LLC, 100424 accreditation.

**THIS IS THE LAST PAGE OF THE REPORT**





## Results of Lead in Drinking Water

Client	<u>BFW Group, LLC</u>	Site Address	<u>Germantown Properties Philadelphia, PA</u>	Sample Date	<u>8/31/2020</u>
Project #	<u>201379</u>			Sample Received Date	<u>8/31/2020</u>
Collected By	<u>Criterion Laboratories, Inc.</u>	Analyzed By	<u>Marrs, Collin</u>	Sample Analysis Date(s)	<u>9/2/2020</u>

---



# Chain of Custody

**Matrix** Water - Potable  
**Analyte** Lead  
**Analysis Type** Graphite Furnace  
**Container** Bottle 250 ml  
**Project** 201379  
**Client** BFW Group, LLC  
**Site Address** Germantown Properties  
 Philadelphia, PA  
**Turnaround** 3 - 5 Days  
**Field Tech** Mary Anne Lerro  
**Sample Notes** Properties have single water source throughout. 63 E Wister (all occupied) and 4949 Germantown has 3 Units (2 Occupied-1 Squatter, 1 Resident). All other properties are single family units.

## Chain of Custody Notes

## Additional Analytes

Sample Number	Location	Description	Received Condition	Date	Notes
201379-07-023-01-01	Kitchen 1st Draw	250 ml 40 E. Wister Street	Good	8/31/2020	
201379-07-023-01-02	Kitchen Flush Draw	250 ml 40 E. Wister Street	Good	8/31/2020	
201379-07-023-01-03	Bathroom 1st Draw	250 ml 40 E. Wister Street	Good	8/31/2020	
201379-07-023-01-04	Bathroom Flush Draw	250 ml 40 E. Wister Street	Good	8/31/2020	
201379-07-023-01-05	Kitchen 1st Draw	250 ml 63 E Wister 1st Floor Unit Kitchen	Good	8/31/2020	
201379-07-023-01-06	Kitchen Flush Draw	250 ml 63 E Wister 1st Floor Unit Kitchen	Good	8/31/2020	
201379-07-023-01-07	Kitchen 1st Draw	250 ml 63 E Wister 2nd Floor Unit Kitchen	Good	8/31/2020	
201379-07-023-01-08	Kitchen Flush Draw	250 ml 63 E Wister 2nd Floor Unit Kitchen	Good	8/31/2020	
201379-07-023-01-09	Kitchen 1st Draw	250 ml 36 E Wister Street	Good	8/31/2020	
201379-07-023-01-10	Kitchen Flush Draw	250 ml 36 E Wister Street	Good	8/31/2020	
201379-07-023-01-11	Bathroom 1st Draw	250 ml 36 E Wister Street	Good	8/31/2020	
201379-07-023-01-12	Bathroom Flush Draw	250 ml 36 E Wister Street	Good	8/31/2020	



# Chain of Custody

201379-07-023-01-13	Kitchen 1st Draw	250 ml 4949 Germantown Avenue Unit C	Good	8/31/2020
201379-07-023-01-14	Kitchen Flush Draw	250 ml 4949 Germantown Avenue Unit C	Good	8/31/2020
201379-07-023-01-15	Bathroom Flush Draw	250 ml 4949 Germantown Avenue Unit C	Good	8/31/2020
201379-07-023-01-16	Bathroom 1st Draw	250 ml 4949 Germantown Avenue Unit C	Good	8/31/2020

**Sample Count**   16  

<b>Handling Chain Type</b>	<b>Handled By</b>	<b>Date</b>	<b>Time</b>	<b>Notes</b>
Report Results To	Melissa Billingsley	8/31/2020	19:36	
Send Reports To	BFW Group, LLC	8/31/2020	19:36	
Samples Taken By	Mary Anne Lerro	8/31/2020	19:36	
Received By	Mary Anne Lerro	8/31/2020	18:00	
Relinquished By	Mary Anne Lerro	8/31/2020	18:00	
Transported By	Mary Anne Lerro	8/31/2020	18:00	
Received By	Craig Hudson	9/1/2020	10:30	
Analyzed By	Collin Marrs	9/3/2020	08:46	



October 22, 2020

**Attention:** PHDC Germantown CNA

**Reference:** Lead XRF Testing Results  
36 E. Wister Street, Philadelphia, PA  
Criterion's Project Number: **201379**

As per your request, Criterion Laboratories, Inc. (Criterion) performed a lead-based paint inspection of the residence located at 36 E. Wister Street in Philadelphia, PA. The purpose of the inspection was to confirm the presence, if any, and condition of lead-based painted surfaces.

Criterion performed a lead-based paint inspection on August 31, 2020. Painted surfaces were analyzed for lead using an X-ray Fluorescence Spectrometer (XRF) manufactured by Thermo Scientific-NITON.

The Environmental Protection Agency (E.P.A.) considers 1.0 milligrams of lead per square centimeter of painted surface, or greater, to be lead-based paint ( $\geq 1.0$  mg/cm<sup>2</sup>).

The City of Philadelphia's Department of Public Health document entitled "Regulations Relating to Labeling, Application and Removal of Lead Paint", dated December 26, 1977, states that any paint lacquer or other applied liquid surface coating, and putty or caulking or other sealing compound with a lead content of 0.7 mg/cm<sup>2</sup> or greater, is considered lead-based.

During the inspection, **no** lead-based paint was detected on any of the components sampled (refer to Attachments).

Sincerely,

A handwritten signature in black ink, appearing to read 'Melissa Billingsley', is written over a light blue horizontal line.

Melissa Billingsley  
Project Manager

Attachments

## Testing Report Legend

### Recommendations

#### **HR – Hazard Reduction**

It is recommended that these surfaces be periodically observed for chalking, peeling or cracking.

If the surface is chalking, it can be cleaned with Trisodium Phosphate and repainted. If it is peeling or cracking, it should be repaired or abated.

#### **AR – Abatement Replacement**

A strategy of abatement that entails the removal of building components coated with lead-based paint and installation of new components free of lead-based paint.

#### **A Encp – Abatement Encapsulation**

“Encapsulant” means a coating or rigid material that relies on adhesion to a lead-based paint surface and is not mechanically fastened to the substrate with a 20-year warranty.

“Encapsulation” means a process to make lead-based paint inaccessible by providing a barrier between the lead-based paint and the environment, where the primary means of attachment for the encapsulant is bonding of a product to the surface covered either by the product itself or through the use of an adhesive.

#### **A Encl – Abatement Enclosure**

“Enclosure” means the installation of a rigid, durable barrier that is mechanically attached to building components, with all edges and seams sealed with caulk or other sealant and having a design life of at least 20 years.

#### **CA – Complete Abatement**

A process designed either to permanently eliminate lead-based paint hazards on a component and includes, but is not limited to: the removal of lead-based paint and lead-contaminated dust.

#### **OSHA**

Any painted surface that has lead content should not be sanded, demolished or disturbed without the proper engineering controls and work methods. As spelled out under OSHA’s CFR Part 1926 Lead Exposure in Construction, Interim Rule. Improper disturbance of any paint with lead content can cause lead to become airborne.

#### **NA – Non-applicable**

X-ray Fluorescence Spectrometer (XRF) results indicated 0.0 or below, which indicates no lead detected by the XRF Spectrometer.

## **Surface/Condition**

### **Surface**

- ◆ A determination of whether a painted surface is considered friction/impact surface or non-friction impact surface.
- ◆ Friction/Impact Surface – any interior or exterior surface subject to abrasion, friction or damage by repeated impact or contact.
- ◆ Non-friction/Impact Surface – any interior or exterior surface not subject to abrasion, friction or damage by repeated impact or contact.

### **Condition**

- ◆ An intact good paint surface is smooth, continuous and free of surface defect, which would result in the release of paint dust or chips.
- ◆ Large surfaces such as walls, floors and ceilings should be rated as follows:
  - ◆ Good or intact condition shall indicate a surface that is entirely intact;
  - ◆ Fair condition shall indicate a surface where less than or equal to two square feet of surface are not intact;
  - ◆ Poor condition shall indicate a surface where more than two square feet of surface are not intact.
- ◆ Components without large surfaces, such as window sills, baseboards, or other small areas, shall be rated as follows:
  - ◆ Good or intact condition shall indicate that the surface is entirely intact;
  - ◆ Fair condition shall indicate that less than or equal to 10 percent of the surface is not intact;
  - ◆ Poor condition shall indicate that more than 10 percent of the surface is not intact.
- ◆ Exterior components with large surface areas shall be rated as follows:
  - ◆ Good or intact condition shall indicate that the surface is entirely intact;
  - ◆ Fair condition shall indicate that less than or equal to ten square feet of surface is not intact;
  - ◆ Poor condition shall indicate that more than ten square feet of surface is not intact.

### **Wall**

When entering a room the wall that is the address side of the room is labeled as “A” Wall. The walls are then labeled in a clockwise fashion as “B” Wall and “D” Wall.



*Calibration Check Test Results*

Client: BFW

Address: 36 E. Wister Street  
Philadelphia, PA

Date: 9-25-2020 XRF Serial #: 25357

Project Number: 201379

Inspector: Michael Martin

Inspector Signature: *Michael A. Martin*

Lead Paint Standards Surface Lead mg/cm <sup>2</sup>	Start of Job 1 <sup>st</sup> Calibration Check		2 <sup>nd</sup> Calibration Check		3 <sup>rd</sup> Calibration Check		4 <sup>th</sup> Calibration Check	
	Reading #	Result	Reading #	Result	Reading #	Result	Reading #	Result
<0.01	1	0.00	62	0.00				
1.04 ± 0.06	2	0.9	63	1.0				
0.71 ± 0.08	3	0.7	64	0.7				
3.58 ± 0.39								
1.53 ± 0.09								
0.31 ± 0.02								
<b>Detector Resolution</b>	373.2							

Note: At least three (3) calibration samples should be taken before and after the inspection has been complete. In addition three (3) calibration samples should be taken at four (4) hour intervals.





Criterion

Client:

BFULLC

### XRF Testing Report

Sampling Location:

36 E. WISTER STREET  
PHILA PA

Room Equivalent:

Front Porch

Room #:

XRF Serial No.:

25357

Date:

8/31/2020

Page 1 of 89

Signature:

*Michael B. Miller*

Project No.:

201339

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm <sup>2</sup>	Results mg/cm <sup>2</sup>	Class. Iocation	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Post	4		Front Porch	0.00	0.00	POS	FRICITION (NON-FRICATION) INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA (N/A)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Hand Rail	5		Front Porch	0.00	0.00	POS	FRICITION (NON-FRICATION) INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA (N/A)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Balustrades	6		Front Porch	0.00	0.00	POS	FRICITION (NON-FRICATION) INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA (N/A)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Roof	7		Front Porch	0.00	0.00	POS	FRICITION (NON-FRICATION) INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA (N/A)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Soices	8		Front Porch	0.00	0.00	POS	FRICITION (NON-FRICATION) INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA (N/A)





Criterion

Client:

BFW LLC

### XRF Testing Report

Page 2 of 89

Sampling Location:

36 E. Cassper Street  
Dills PA

Date:

8/31/2020

Room Equivalent:

Front Porch

Signature:

*[Signature]*

Project No.:

201379

Room #:

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm <sup>2</sup>	Results mg/cm <sup>2</sup>	Class. Location	Surface/Condition	Recommendation
TRW	Wood Brick Sheetrock Plaster (Metal) Concrete	Electric Metal Box	9		Front Porch	0.00		POS NEG	FRICITION NON- FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
Brown	Wood Brick Sheetrock Plaster Metal Concrete	Floor	10		Front Porch	0.00		POS NEG INC	FRICITION NON- FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
	Wood Brick Sheetrock Plaster Metal Concrete							POS NEG INC	FRICITION NON- FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
	Wood Brick Sheetrock Plaster Metal Concrete							POS NEG INC	FRICITION NON- FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A





Criterion

Client:

BFD LLC

### XRF Testing Report

Sampling Location:

36 E. WILSON STREET  
PHILA PA

Date:

8/31/2020

Room Equivalent:

Signature:

*Michael H. Miller*

Project No.:

201370

Room #:

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm	Results mg/cm <sup>2</sup>	Class. Imitation	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	11		Front Door	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	12		Front Door	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	13		Front Door	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	14		Living Room	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	15			0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	16			0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	17			0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A
White	Wood Brick Sheetrock Plaster Metal Concrete	Window Sill	18		Living Room	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCP CA OSHA N/A





Criterion

Client:

RFULLC

### XRF Testing Report

Sampling Location:

36 E. WISTER STREET  
PHILA PA

Room Equivalent:

Room #:

Date:

8/31/2020

Signature:

*Michael A. MSTD*

Project No.:

201379

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm	Results mg/cm <sup>2</sup>	Class. location	Surface/Condition	Recommendation	
GRAY	Wood Brick Sheetrock Plaster Metal Concrete	Walls	19	1	Dining Room / Kitchen	0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
			20	2		0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
			21	3		0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
			22	4		0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
white	Wood Brick Sheetrock Plaster Metal Concrete	Windows Sill	23		Dining Room / Kitchen	0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
			24			0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
			25			0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
white	Wood Brick Sheetrock Plaster Metal Concrete	Door Jam	26		Rear Door To yard	0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
						0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
white	Wood Brick Sheetrock Plaster Metal Concrete	Door Casings			Rear Door To yard	0.00	0.00	POS	FRICITION NON-FRICITION	INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A





XRF Testing Report

Criterion Client:

BFW LLC

Sampling Location:

36 Lewis Ter Street  
Phila PA

Room Equivalent:

Room #:

Date:

8/31/2020

Signature:

Melvin A. White

Project No.:

201379

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm <sup>2</sup>	Results mg/cm <sup>2</sup>	Class-ification	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	27		Utility closet	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	28		Utility closet	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	29		Utility closet	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	FLAT TOP PAI	30		Stairwell	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Stairnger	31		Stairwell	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A





Criterion

Client:

BFW LLC

### XRF Testing Report

Sampling Location:

36 Elm Street  
Phila PA

Room Equivalent:

Room #:

Signature:

*[Signature]*

Date:

8/31/2020

Project No.:

201379

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm	Results mg/cm <sup>2</sup>	Class-Location	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	WALL	32	1	2nd Fl - Front Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
			33	2		0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
			34	3		0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	DOOR	35	4	2nd Fl - Front Bedroom	0.00	0.00	INC	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
			36			0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	DOOR	37		2nd Fl - Front Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
			38			0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	DOOR	39		2nd Fl - Front Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
			34			0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A
White	Wood Brick Sheetrock Plaster Metal Concrete	Sill			2nd Fl - Front Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT	HR AR A ENCL A ENCP CA OSHA N/A





XRF Testing Report

Criterion Client: AFW LLC

Sampling Location: 36 E. Quister Street

Room Equivalent: PHILA Pk

Room #: \_\_\_\_\_

Date: 8/31/2020

Signature: [Signature]

Project No.: 201874

XRF Serial No.: \_\_\_\_\_

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm <sup>2</sup>	Results mg/cm <sup>2</sup>	Class.	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	WALLS	40	1	Sud P - Berke Left Bedroom	0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			41	2		0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			42	3		0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	43	2	Sud P - Berke Left Bedroom	0.00	0.00	INC	NON-FRIC (POOR)	A ENCL (N/A)
			44			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			45			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	46		Sud P - Berke Left Bedroom	0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			47			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			48			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
White	Wood Brick Sheetrock Plaster Metal Concrete	Windows Sill	49		Sud P - Berke Left Bedroom	0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			50			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)
			51			0.00	0.00	POS	FRIC (INTACT)	HR (A ENCP)





# XRF Testing Report

Criterion

Client:

BFW LLC

Sampling Location:

36 E. Wister Street  
Phila PA

Room Equivalent:

Room #:

Date:

8/31/2020

Signature:

*Michael A. White*

Project No.:

201379

XRF Serial No.:

25357

Color	Substrate	Component	Reading No.	Wall	Test Location	XRF Reading mg/cm <sup>2</sup>	Results mg/cm <sup>2</sup>	Class-Location	Surface/Condition	Recommendation
TAN	Wood Brick Sheetrock Plaster Metal Concrete	WALLS	48	1	2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	49	2	2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	50	3	2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	51	4	2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	52		2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	53		2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	54		2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
TAN	Wood Brick Sheetrock Plaster Metal Concrete	Door	55		2nd Fl - Rear Right Bedroom	0.00	0.00	POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A
White	Wood Brick Sheetrock Plaster Metal Concrete	Window Sill						POS	FRICITION NON-FRICITION INTACT FAIR POOR	HR AR A ENCL A ENCP CA OSHA N/A









October 9, 2020

**Attention:** PHDC Germantown CNA

**Reference:** Radon Testing Results  
36 E. Wister Street, Philadelphia, PA  
Criterion's Project Number: **201379**

Enclosed are the laboratory results concerning the radon testing performed at the residence located at 36 E. Wister Street in Philadelphia, PA. Sampling was performed by Safe Shelter Environmental from September 22- September 24, 2020.

A radon sample was collected from the First Floor of the home, results indicated an average radon level of 5.8 picocuries per liter (pCi/L). This is **above** the United States Environmental Protection Agency's (US EPA) recommended indoor residential level of 4 pCi/L.

Attached is the EPA Citizen's Guide to Radon, which explains what the testing results mean and how to lower radon levels. In general, installing a vent system in the basement is the best way to reduce radon levels in a building.

Sincerely,

A handwritten signature in black ink, appearing to read 'Melissa Billingsley', is written over a light blue horizontal line.

Melissa Billingsley  
Project Manager

Attachment



**RADON TEST RESULTS**

**Test # 200913146**

**REPORT DATE: 9/25/2020**

**CLIENT INFORMATION**

**TEST LOCATION**

<b>NAME</b>	Ms. Melissa Billingsley			<b>NAME</b>	
<b>ADDRESS</b>	Criterion Labs, Inc.			<b>ADDRESS</b>	36 E. Wister Street
	400 Street Road				Philadelphia, PA 19144
	Bensalem, PA 19020			<b>COUNTY</b>	Philadelphia
<b>PHONE #</b>	(215) 244-1300	<b>FAX #</b>	(215) 244-4349	<b>STRUCTURE</b>	two story rowhome
<b>EMAIL</b>	mbillingsley@criterionlabs.com				

**COMMENTS:** Pre-Mitigation ( yes ) Tested under closed house conditions ( yes )  
 Occupied ( ) Crawl Space vents open: ( N/A )

**TEST DEVICE - E-PERM**

**Electret Reader Serial Number: B-89-RE-161 Reader calibration expiration date: 10/24/2020**

DEVICE ID #	DEVICE LOCATION	START DATE	START TIME	FINISH DATE	FINISH TIME	RESULT	UNIT
SLW053	first floor	9/22/2020	10:35	9/24/2020	10:05	5.3	pCi/L
SLV977	first floor DUP	9/22/2020	10:35	9/24/2020	10:05	6.3	pCi/L

**AVERAGE RADON LEVEL 5.8 pCi/L**

The average radon level of **5.8 pCi/L** falls **ABOVE** the EPA recommended action level of 4.0 pCi/L

*Radon Health Risk Information*

Radon is the second leading cause of lung cancer, after smoking. The U.S. Environmental Protection Agency (EPA) and the Surgeon General strongly recommend taking further action when the home's radon test results are 4.0 pCi/L (.02 WL)\* or greater. The national average indoor radon level is about 1.3 pCi/L. The higher the home's radon level the greater the health risk to you and your family. Reducing your radon levels can be done easily, effectively and fairly inexpensively. Even homes with very high radon levels can be reduced below 4.0 pCi/L. For further information about reducing elevated radon levels please refer to the "Pennsylvania's Consumer's Guide to Radon Reduction."

**TEST PLACED BY:**

**Rick Haag PA-DEP# 0199**

**TEST RETRIEVED BY:**

**Rick Haag PA-DEP# 0199**

**SAFE SHELTER RECOMMENDS THAT RADON TESTING BE PERFORMED IN ALL STRUCTURES AT LEAST ONCE EACH YEAR**

*Notice to Clients: The Radon Certification Act Requires that anyone, who provides any Radon related service or product to the general public, must be certified by the Pennsylvania Department of Environmental Protection. You are entitled to evidence of certification from any person who provides such services or products. You are also entitled to a price list for services or products offered. All radon measurement data will be sent to the Department as required in the Act, and will be kept confidential. If you have any questions, comments or complaints concerning persons who provide Radon related services, please contact the Department at the Bureau of Radiation Protection, Department of Environmental Protection, PO 8469, Harrisburg, PA 17105-8469, (717) 783-3594.*

### *8.3.3 TENANT QUESTIONNAIRES*

---

## The Maple Corporation and Germantown Housing Justice

### Germantown / Mt. Airy Resident Questionnaire (PCNA)

Date Interviewed:	<b>8/24/2020</b>
Name:	<b>Kenya Carter</b>
Address:	<b>36 E. Wister St</b>
Number of occupants:	<b>7</b>
Length of Occupancy:	<b>9</b>
Bedrooms:	<b>4</b>
Baths:	<b>2</b>
Unit Type: Single, Duplex, Triplex, Multifamily	<b>Single</b>
Proposed Inspection date	<b>8/31/2020</b>
Did you receive letter?	<b>Y</b>
*Radon process notification	<b>Y</b>
Are there any health concerns in relation to inspection/Covid-19?	<b>N</b>
Comments	
Are there mobility or ease of use concerns related to entering your unit, bathroom, and kitchen?	<b>N</b>
Do you notice any unusual odors in or directly outside your home?	<b>Sometimes-sewer smell</b>
Is mold present in your unit?	<b>Y</b>
If so, has it been reported?	<b>Y</b>
Have you had any recent repairs or replacements in your unit?	<b>Y</b>
If so, what was repaired or replaced?	<b>Window in back, railing, doorbell</b>
Basement, if applicable Condition - Very good , Good, Poor, Very Poor Comment	<b>N/A</b>
Living Room Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b> <b>Leak in ceiling, walls &amp; ceiling was replaced</b> <b>rodents tunneling thru walls from 38 Wister</b>
Dining room Condition - Very good , Good, Poor, Very Poor Comment	
Kitchen Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b> <b>Cabinets fell off wall, pipes keep bursting</b> <b>mold from water damage, PHA came in</b> <b>but did not repair</b>
Bedroom 1 Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b> <b>Very Drafty windows, poor carpet</b>
Bedroom 2 Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b> <b>Very Drafty windows, poor carpet</b>
Bedroom 3 Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b> <b>Very Drafty windows, poor carpet</b> <b>Also 4th bedroom</b>
Bathroom(s) Condition - Very good , Good, Poor, Very Poor Comment	<b>Poor</b> <b>1br-pipes leaking, caulking damaged</b> <b>2br-faucet broken</b>

Interior railings Condition - Very good , Good, Poor, Very Poor Comment	<b>No railings PHA measured but never installed</b>
Exterior doors Condition - Very good , Good, Poor, Very Poor Comment	<b>Good</b>
Exterior stairs Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor wooden and not stable</b>
Exterior walls Condition - Very good , Good, Poor, Very Poor Comment	<b>Good Front window caulked closed due to water damage</b>
Exterior railings Condition - Very good , Good, Poor, Very Poor Comment	<b>N/A</b>
Roof Condition - Very good , Good, Poor, Very Poor Comment	<b>Good</b>
Gutter Condition - Very good , Good, Poor, Very Poor Comment	<b>Good</b>
Plumbing system Condition - Very good , Good, Poor, Very Poor Comment	<b>Very Poor</b>
Water pressure Condition - Very good , Good, Poor, Very Poor Comment	<b>Good</b>
What type of heating system do you have? Condition - Very good , Good, Poor, Very Poor Comment	<b>Gas Very Poor Every winter it requires service (mice ate through casing)</b>
Do you have central air? Condition - Very good , Good, Poor, Very Poor Comment	<b>No</b>
Do you have smoke detectors?	<b>Y</b>
Do you have carbon monoxide detectors?	<b>N</b>
Is there evidence of infestation in your home?	<b>mice, roaches (not a lot)</b>
If yes, did you report it to management?	<b>Y-mice are pretty prevalent</b>
Do you currently need special modification to your home?	<b>No</b>
If so, please explain	
General Questions or Concerns	